

Service Desktop Utility Machine Health Browser

- Error Logs
- Diagnosis
- Image Quality
- Calibration
- Configuration
- Utilities
- Replacement
- PM

System Information		
Item	Information	Status
SW Version	HD3 0	
Facility	Exp. Specjalistyczny Nowy Saz	
Suite Name	CT01	
System Type	Discovery CT	
Unique System Number	insite not checked out yet	
System ID	PL1063CT01	
IP Address	10.3.0.1	Interface eth2
Access Level	Non-proprietary	Invalid
Software Installation Date	Wed 18 Jul 2018 01:05:14AM	
DASH Camera	unknown	Not Installed
DICOM Network Cameras	2 Camera(s)	Installed
Installed Tube	Perseus	
Tube Install Date	Mon Feb 19 20:27:28 2018	Total Patient Exams: 21,233
Data Acquisition System	HDAS HD 64	
Power Distribution Unit	NGPDU	

Auto Update
Frequency (sec) 10

Current System Status		
Item	Information	Status
System Date	Tue, Sep 3, 2019	
System Time	14:11:46 CEST	
Application Info	14MW247_SP2-0-10_V40_PS_HD64_G_GTL	running
New Patient Exam	9135	
SW Updates	Manual Installation Required	No

Cleanup System Resets

Images: 0

Image	Date	Image Size